

Hardware for Output Transformers	
Qty	Description
4	4-40 X 3/4 Machine Screws / Phillips / Pan Head / Steel / Zinc
4	4-40 Hex Machine Screw Nuts / Steel / Zinc
8	#4 Medium Split Lockwashers / Steel / Zinc

Hardware for main PCB	
Qty	Description
7	4-40 X 3/16 Machine Screws / Phillips / Flat Undercut / 18-8 Stainless Steel
3	4-40 X 3/16 Machine Screws / Phillips / Pan Head / Steel / Zinc
5	3/16 Hex Standoffs (Female / Female) / Aluminum / 4-40 X 1/4
3	#4 Medium Split Lockwashers / Steel / Zinc

Hardware for filter PCB	
Qty	Description
4	4-40 X 1/4 Machine Screws / Phillips / Pan Head / Steel / Zinc
2	3/16 Hex Standoffs (Female / Female) / Aluminum / 4-40 X 3/4
4	#4 Medium Split Lockwashers / Steel / Zinc

